

STIRLING

POWDERS



Black Ferrotex




Black Ferrograin



Grey (Autumn)



Grey (Admarality)



Grey (Ocean)



Silver




Antique Silver



White Ferrotex



White Ferrograin



Red Ferrotex



Bronze



Gold



Pink Ferrotex



Green Ferrotex (Lime)



Blue Ferrotex

GENERAL CARE AND MAINTENANCE

Chrome, anodised, polished or powdercoated metal surfaces

Clean with a damp, soft cloth or sponge using lukewarm soapy water. Strong detergents which contain bleach, acid or have an abrasive effect (such as scouring creams) should be avoided. Sponges and scourers made from synthetic fibres or metal which may leave permanent scratches on the surfaces should also be avoided. Ensure product is dried with clean fibre-free cloth after washing.

Stainless Steel

Stainless steel needs constant care and preventative maintenance. The surface needs to be wiped dry of moisture daily. This is to prevent the moisture being trapped under a cover of dust or seaspray which results in Tea staining. Stainless steel should be cleaned with 'White Lilly' cream cleaner (no abrasive) or a stainless-steel cleaner - usually in a spray can. Wipe over surface in direction of finish lines.

